

 Sede: Via Antica, 24/3
 Filiale:

 33048 S. Giovanni al Nat. UD
 Via Braille, 5

 Tel. 0432.747211 r.a.
 20851 Lisson

 Fax 0432.747250
 Tel. 039.4643

 http://www.catas.com
 Fax 039.4643

 e-mail: lab@catas.com
 e-mail: lisson

Filiale: Via Braille, 5 20851 Lissone MB Tel. 039.464567 Fax 039.464565 e-mail: lissone@catas.com

Date received: 19-04-12

Date of issue: 10-05-12

Report consists of 2 test reports.

Defects before testing: None

Sample name: GLISS 970

PEDRALI S.P.A. STRADA PROVINCIALE 122 24050 MORNICO AL SERIO (BG) ITALIA

TEST REPORT N° 140549

Overall dimensions: 520 x 485 x 1065 (h) mm

List performed tests:

- 1. Seat and back static load test EN 1728:2000
- 2. Seat and back fatigue test EN 1728:2000



This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

aging Director Andrea Giavon

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer.



Sede: Via Antica, 24/3 33048 S. Giovanni al Nat. UD Via Braille, 5 Tel. 0432.747211 r.a. Fax 0432.747250 http://www.catas.com e-mail: lab@catas.com

Filiale: 20851 Lissone MB Tel. 039.464567 Fax 039.464565 e-mail: lissone@catas.com

TEST REPORT N° 140549

Date of issue: Sample weight Sample name:

10-05-12 Not determined GLISS 970



Side view



Rear view



Bottom view

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer.



Sede: Via Antica, 24/3 33048 S. Giovanni al Nat. UD Via Braille, 5 Tel. 0432.747211 r.a. Fax 0432.747250 http://www.catas.com e-mail: lab@catas.com

Filiale: 20851 Lissone MB Tel. 039.464567 Fax 039.464565 e-mail: lissone@catas.com



TEST REPORT 140549 / 1

Date received:	19-04
Date of test:	26-04
Date of issue:	10-05
Sample name:	GLIS



PEDRALI S.P.A. **STRADA PROVINCIALE 122** 24050 MORNICO AL SERIO (BG) ITALIA

Seat and back static load test EN 1728:2000

Seat and back static load test, clause 6.2.1

Test results:

Seat load	Back force	Number	Remarks
N	N	of cycles	
2.000	500	10	No defects

Note:

According to EN 1728:2000, horizontal force has been reduced from 7000 N to 500 N, to avoid tipping.

Seat front edge static load, clause 6.2.2

Seat load N	Number of cycles	Remarks
2.000	10	No defects

Note:

The test has been carried out according to table 1 of EN 15373:2007, level 3 - severe.

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Manlaging-Director Andrea Giavon

The sample name and, when relevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer. pag. 1/1



Sede: Via Antica, 24/3 33048 S. Giovanni al Nat. UD Tel. 0432.747211 r.a. Fax 0432.747250 http://www.catas.com e-mail: lab@catas.com

Filiale: Via Braille, 5 20851 Lissone MB Tel. 039.464567 Fax 039.464565 e-mail: lissone@catas.com



140549 / 2

Date received:	19-04-
Date of test:	26-04-
Date of issue:	10-05-
Sample name:	GLISS



PEDRALI S.P.A. STRADA PROVINCIALE 122 24050 MORNICO AL SERIO (BG) ITALIA

Seat and back fatigue test EN 1728:2000

Seat and back fatigue test, clause 6.7

Test results:

Seat force N	Back force N	Number of cycles	Remarks
1.000	300	200.000	No defects

Note:

The test has been carried out according to table 1 of EN 15373:2007, level 3 - severe.

This document is validated by digital signature and time stamping in accordance with the Italian laws and the European Directives which regulate the electronic signature systems.

Managing Director Dr. Andrea Giavon

The sample name and, when felevant, its description, are given by the orderer, and CATAS does not assume responsibility on this matter. This test report relates to the sample submitted for the test and no others. Additions, deletions or alterations are not permitted. This test report must always be reproduced in its entirety. Unless otherwise stated, sampling has been carried out by the orderer. pag. 1/1